



Automatic-butt-fastening set 5, galvanized Reference: SS-STV-5-SZ

Consists of:

Self tapping screw 5 with through hole, St, galvanized

Self tapping screw 5 with threaded hole, St, galvanized

Screw M4x40, St, galvanized

M = 2.5 Nm

m = 11.0 g

With thread form-butt fastening sets two same sized profiles can be assembled at the end faces. It is recommended to always use the connectors in pairs. No additional machining is required to assemble the connector. The connector sleeves are inserted into the slots on the face side. The thread is self-forming and is screwed in using a hand drill with counter-clockwise rotation.